



འབྲུག་རྒྱལ་ཁབ་ལྷན་དུས་ལྷན་ཚན་པོ།
Food Corporation of Bhutan Limited
"Ensuring Food Security for the Nation at all times"
CORPORATE HEAD OFFICE



FCBL/DoCB/EED/TU/01/ 588

15/12/2022

SEALED QUOTATION

The Food Corporation of Bhutan Limited (FCBL) invites sealed quotations from the interested reputed vehicle workshops based in Phuentsholing, Thimphu, Gelephu and Samdrup Jongkhar to carry out repair and maintenance works of FCBL vehicles (Light, Medium and Heavy). The terms and conditions are mentioned below and the details of works for quoting labour rates are enclosed.

The interested workshop owners may quote the labor rates for the following vehicle brands at the respective locations as per Annexure-I. (Eg: *Phuentsholing workshop owners should quote for only Phuentsholing and likewise for other regions*)

1. **THIMPHU** - MISTUBISHI, BOLERO PICKUP & EICHER PRO 10.49
2. **GELEPHU** - EICHER 10.80, TOYOTA, BOLERO EICHER PRO 10.49&JUMBO 20.16
3. **S/JONGKHAR** - EICHER 10.80, TOYOTA, BOLERO EICHER 10.49&JUMBO 20.16
4. **P/LING RO-**, EICHER 10.80, JUMBO 20.16, EICHER PRO 10.49, ISUZU MISTUBISHI, TOYOTA& EECO

The quotations should be submitted to the office of Regional Director, FCBL, Phuentsholing/Thimphu/Gelephu/Samdrup Jongkhar respectively on or before 29thDecember, 2022 at 11:00AM and will be opened on the same day at 11:30 AM. For further details please contact Motor Transport Officer, FCBL Phuentsholing at 252505/17423101 during office hours only.

Terms and conditions


1. The rate should be inclusive of all the taxes/charges and should be valid for 12 months.
2. The successful bidder should carry out the Repair& Maintenance works of FCBL vehicles as per their rate quoted. In the event of any additional labour charges claimed which are not mentioned in the bid, payment shall not be made.
3. Spares shall be purchased by FCBL from the reputed spares dealers and shall be provided to the workshop.
4. The sum of Nu.10,000/-shall be furnished as security deposit money along with the quotation, which may be submitted in the form of either bank guarantee/Cash warrant in favor of FCBL or deposit in cash with FCBL (i.e. FCBL money receipt to be enclosed along with the bid).
5. The security deposit of the bidders shall be refunded after the award of the tender to the successful bidder.
6. The security deposit of the successful bidder shall be kept as the performance security.



ཕྱུ་འབྲུག་བཟའ་སྲོད་ལས་འཛིན་ཚད།
Food Corporation of Bhutan Limited
"Ensuring Food Security for the Nation at all times"
CORPORATE HEAD OFFICE



7. If the works are not found satisfactory, the workshop shall rectify the defect at their own cost.
8. The labour rate should be quoted in the FCBL format as per the attachment in Annexure-I.
9. FCBL reserves the right to accept or reject the quotations without assigning any reasons.
10. The decision of the tender committee shall be final and bidding.


FCBL Management




Annexure-I

FOR 2023 JOB DESCRIPTION	HEAVY VEHICLES				LIGHT VEHICLES				
	JUMBO 20.16	EICHER 10.80	EICHER 10.49	TATA 407	TOYOTA HILUX	TOYOTA L/CRUIS ER	ISUZU HILUX	MISTUBS HI L200	MAHINDR A PICK UP
ENGINE									
1 Engine Overhauling									
2 Cylinder Head changing									
3 Head gasket changing									
4 Pistion ring changing									
5 Cylinder head lightening									
6 Tappet adjusting									
7 Push rod changing									
8 Engine valve changing									
9 Main bearing oil seal changing									
10 Exhaust manifold changing									
11 Oil pump changing									
12 Air compressor changing									
13 Timing cover oil seal changing									
14 Oil cooler plate changing									
15 Oil cooler 'O' ring changing									
16 Oil sump changing									
17 Engine mounting changing (per pad)									
18 Cabin mounting changing									
19 Engine oil filter changing									
20 Diesel filter changing									
21 Engine oil changing									
22 Engine oil pipe changing									
23 Rocker arm/shaft changing									
24 Fly wheel fitting									
25 Vibration damper pully fitting									
26 Radiator fitment									
27 Radiator servicing									
28 Radiator hose fitment									
29 Cooling line pipe fitment									
30 Thermostat fitment									
31 Air cleaner fitment									
32 Fan replacement									
33 Fan belt changing									
34 Water pump changing									
35 Power strg.belt changing									
36 Fuel tank serviceing									
37 Tappet cover packing changing									
38 Radiator Gas pipe change									
39 Acclerator cable change									
40 Controlling end change									
41 Cam Shaft bush replacement									
42 Turbo Oil pipe change									
43 Cross member change									
44 Drag Kit change									
45 Body nut and bolt tightining									
46 Seat repairing									



FOR 2023 JOB DESCRIPTION		HEAVY VEHICLES				LIGHT VEHICLES				
		JUMBO 20.16	EICHER 10.80	EICHER 10.49	TATA 407	TOYOTA HILUX	TOYOTA L/CRUIS ER	ISUZU HILUX	MISTUBS HI L200	MAHINDR A PICK UP
47	Air pressure pipe change									
48	Fan Drive belt replacement									
F.I.P/NOZZLE										
1	F.I.P overhauling									
2	Nozzle overhauling(each)									
3	FIP & nozzle calibrating									
4	FIP & nozzle removal/fitment									
5	FIP& nozzle removal/fitment (each)									
6	Feed pump changing									
7	Fuel filter changing									
8	Fuel filter servicing									
9	Fuel HP pipe fitting (each)									
10	Fuel hose fitting									
11	Fuel pump Gasket change									
12	By pass fimter changing									
CLUTCH										
1	Clutch plate changing									
2	Pressuer plate changing									
3	Release bearing changing									
4	Clutch master cylinder UP/LO changing									
5	Clutch sleeve cylinder changing									
6	Clutch pedal adjusting									
7	Pressure plate finger adjustment									
GEAR BOX										
1	Gear box removal /fitment									
2	Gear box overhauling									
3	Gear box top coverhauling									
4	Gear box oil seal changing									
5	Gear lever fitment									
6	Gear cable change									
7	Gear linkage adjustment									
8	Gear box oil changing									
SUSPENSION										
1	Front spring leaf changing(per loc)									
2	Rear spring leaf changing (per loc)									
3	Front spring recambering (per set)									
4	Rear spring recambering(per set)									
5	Spring hanger change									
6	Staplizer bush change									
7	Chassis U bolt change									
8	Fan Belt change									
9	Shackle pin /bush changing (per set)									
10	Shock absorber changing									
11	Spindle bush remmering/Refitting									
12	Spring Hanger change RR/FF									
13	Spring 'U' bolt RR/FF change									
14	Spring bush RR/FF set change									



FOR 2023 JOB DESCRIPTION		HEAVY VEHICLES				LIGHT VEHICLES				
		JUMBO 20.16	EICHER 10.80	EICHER 10.49	TATA 407	TOYOTA HILUX	TOYOTA L/CRUIS ER	ISUZU HILUX	MISTUBS HI L200	MAHINDR A PICK UP
15	Center bolt changing									
FRONT AXLE										
1	Steering box overhauling(MANUAL)									
2	Steering box removal/fitment									
3	King pin overhauling per wheel									
4	Tie rod end /draglink changing									
5	Staplizer bush changing									
6	Steering box oil seal changing									
7	Steering wheel removal / fitmebt									
8	Steering UJ cross fitment									
9	Steering column bracket fitment									
10	Steering free play adjustment									
11	Power steering cyl./ pump replacement									
12	Front axel removal /fitment									
13	Hubs greasing (per wheel)									
14	Drive shaft oil seal changing									
15	Power steering gear box removing/refitting									
REAR AXEL										
1	Rear axel assembly removal / fitment									
2	Crown overhauling									
3	Differential packing changing									
4	Tail pinion oil seal changing									
5	Differential oil changing									
6	Hubs gresing (per wheel)									
7	Cross bearing change									
8	Axel shaft changing									
PROPELLER SHAFT										
1	Propeller shaft removal /fitment (each)									
2	Proppeller shaft cross fitment (each)									
3	Propeller shaft yoke teeth									
4	Stapney Tyre cable change									
5	Spare Tyre machine change									
6	Controlling link change									
7	Center bearing changing									
BRAKES										
1	Underloader valve changing									
2	Master cyl. Replacement upper /Lower									
3	Wheel cyl.replacement (per wheel)									
4	Brake lining changing									
5	System protection									
6	Wheel nuts and bolts changing									
7	Brake drum changing									
8	Brake pipe changing (per location)									
9	Exhaust brake valve changing									
10	Exhaust brake adjusting									
11	Hand brake valve changing									
12	Brake adjusting (per wheel)									

FOR 2023 JOB DESCRIPTION		HEAVY VEHICLES				LIGHT VEHICLES				
		JUMBO 20.16	EICHER 10.80	EICHER 10.49	TATA 407	TOYOTA HILUX	TOYOTA L/CRUIS ER	ISUZU HILUX	MISTUBS HI L200	MAHINDR A PICK UP
13	Controlling butterfly changing									
14	Controlling link checking									
15	Dualbrake overhauling									
16	Wheel alignment									
17	Brake boster changing									
18	Brake servicing front(per wheel)									
19	Brake servicing rear									
20	Brake shoe changing (per wheel)									
21	Slack adjuster replacement									
22	Cam bush FF/RR change									
23	DDU kit change									
24	Brake cam bush change									
ELECRTICAL										
1	Self starter overhauling									
2	Self starter servicing									
3	Solenoid switch changing									
4	Self removal /fitment									
5	Alternator overhauling									
6	Alternator servicing									
7	Alternator removal/fitment									
8	Battery changing									
9	Battery recharging									
10	Wiper motor changing									
11	Electrical line checking									
12	Head lamp bulb fitting									
13	Head lamp assembly fitting									
14	Bulb fitting (each)									
15	Backlight fitting									
16	Indicator fitting									
17	Horn fitting									
18	Speedo meter cable fitting									
19	Battery pole making									
20	Tank unit fitting									
21	Instrument pannel removing/refitting									
22	Wiper relay intermittent replacement									
23	Wiper blade changing (per piece)									
BODY										
1	Windshield glass fitting(rubber)									
2	Door glass fitting (each)									
3	Door lock fitting									
4	Inner door lock fitting									
5	Fog light circuit making									
6	Vacuum horn making									
7	Chassis'U' Bolt changing									
8	Body mountain checking/repairing									
9	Body bush changing									
SERVICING										
1	Servicing									



FOR 2023 JOB DESCRIPTION		HEAVY VEHICLES				LIGHT VEHICLES				
		JUMBO 20.16	EICHER 10.80	EICHER 10.49	TATA 407	TOYOTA HILUX	TOYOTA L/CRUIS ER	ISUZU HILUX	MISTUBS HI L200	MAHINDR A PICK UP
2	Nipple greasing									
MACHINING JOB										
1	Engine block boring									
2	Engine block resieeing									
3	Crank shaft grinding									
4	Cam bush fitting&line boring									
5	Connecting bush fitting &line boring									
6	Cam shaft polishing									
7	A.C journal grinding									
8	Parent bore checking									
9	7no.journal remetalling/repair									
10	Block facing									
11	Cylinder head facing									
12	Valve seat cutting&fitting									
13	Valve guide cutting&fitting									
14	Differential tube remetalling/threading									
15	Bavel box remetalling/facing									
16	Brake drum turning									
17	Fly wheelturning									
18	Door glass adjust									
19	Pressure plate turning									
20	King pin bush remarring									
21	Stering cross assy changing									
22	Stepney Tyre cable/Machine change									
23	Spring hanger changing									

